Water Conditions Update



Board of Directors Meeting February 26, 2024




Weather Forecasted Turnout 2024 SWP SWP & Hydrologic Valve **Allocation & Deliveries &** Reservoir and Snow Inspections Water Recharge Conditions Conditions Portfolio













State Precipitation Stations – North Sierra












Lake Oroville Reservoir Levels





Ř



San Luis Reservoir Levels








stablished 1

Forecasted Hydrologic Conditions



CURRENT REGIONAL SNOWPACK FROM AUTOMATED SNOW SENSORS

% of April 1 Average / % of Normal for This Date



NORTH	
Data as of February 21, 2024	
Number of Stations Reporting	25
Average snow water equivalent (Inches)	22.7
Percent of April 1 Average (%)	79
Percent of normal for this date (%)	100

CENTRAL	
Data as of February 21, 2024	
Number of Stations Reporting	50
Average snow water equivalent (Inches)	18.0
Percent of April 1 Average (%)	67
Percent of normal for this date (%)	84

SOUTH	
Data as of February 21, 2024	
Number of Stations Reporting	28
Average snow water equivalent (Inches)	14.2
Percent of April 1 Average (%)	64
Percent of normal for this date (%)	79

STATE	
Data as of February 21, 2024	
Number of Stations Reporting	103
Average snow water equivalent (Inches)	18.1
Percent of April 1 Average (%)	69
Percent of normal for this date (%)	86

Statewide Average: 69% / 86%




Sierra Nevada Mountain Snowpack

CONO PASS IL ITER

Historic SWP Allocations


SGPWA Port	folio @ 15%	
Source	TOTAL (AF)	Delivered
SWP – Carryover SGPWA	8,650	
SWP – Carryover Ventura	4,178	✓
SWP – Table A	2,595	
SWP – Ventura	1,500	
Subtotal SWP	<u>16,923</u>	
Non-SWP - Nickel Water	1,700	
Total	18,623	



O PASS



2024 SWP Allocation & Portfolio Update



A DE CALIFORITE

*Estimated *From Local Storage







BCVWD Recharge Facilities





Brookside East Recharge Facility

February Recharge Activities

Cla-Val Valve Inspections

- Both Mountain View and Noble Creek turnout valves inspected

-Inspections included: overall valve condition assessment and internal parts cleaning

-Overall valve conditions are good with some maintenance recommendations given







Mountain View Valve Inspection







Noble Creek Valve Inspection